

Inspection Photos
Operator: BP America
API#: 067-09299
Date: 3/2/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern fill slope, revegetation is in a grazed condition with grasses such as crested wheatgrass, similar to surrounding pasture vegetation. Weed debris needs to be removed and properly disposed of.



Photo 3. View of reference area vegetation comprised of grazed pasture. Grasses not in identifiable condition at this time.