

Inspection Photos
Operator: BP America
API#: 067-08377
Date: 3/2/2020



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the southern fill slope, revegetation is progressing with grasses such as sand dropseed and western wheatgrass, as well as weeds such as cheatgrass and yellow tumbled mustard.



Photo 3. View of Russian knapweeds within the southern project area.




Photo 3. View of more Russian knapweeds and weed debris within the southern project area.



Photo 3. View of reference area vegetation comprised of pinyon and juniper woodland with herbaceous understory.