

Inspection Photos

Location Name: LARAMIE ENERGY LLC Domestic Tap /18-12 Pad

Location ID: 455944



Photo #0632 from entrance to location



Photo #0629 domestic tap is derived from the back side casing valve.

Location ID: 455944



Photo #0628 Railroad unions and cast fittings.

Inspection Photos

Location Name: LARAMIE ENERGY LLC Domestic Tap /18-12 Pad

Location ID: 455944



Photo #0631 Torpedo scrubber.