

Inspection Photos

Loc#335053

Operator: Ursa

Inspection #: 692401918

Inspection Date: 2/21/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:

Views of Location from entry. Insert of PR Well API#045-12200; refer to next slide.

February 21, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Ursa CSF Loc#335053



Photo#2:

COGCC Maps has PR Well API#045-12200 located in wrong position.

February 21, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Ursa CSF Loc#335051



Photo#3:
Views of Location and unknown associated equipment/ risers.

February 21, 2020