

## Pit Status Evaluation Form

### Pit Overview:

<b>Pit Name:</b> HAMILTON 1-3	<b>Facility ID:</b> 114683
<b>Current Status:</b> Unknown	<b>Status Date:</b> 9/23/1999
<b>Current Operator:</b> JACKSON* DONALD W / 44352	
<b>Updated Operator:</b>	
<b>Form 15 Pit Permit Doc #:</b>	<b>Permit Date:</b>
<b>Related Facilities:</b> HAMILTON, EMMA #1-3 (API 05-009-06077, Facility ID 205666, Loc ID 320979)	

<b>County:</b> BACA			
<b>Township:</b> 35S	<b>Range:</b> 41W	<b>Section:</b> 3	<b>QQ:</b> NESW
<b>Original Latitude/ Longitude:</b> 37.023757 / -102.049813			
<b>Updated Latitude/ Longitude:</b> /			
<b>Basis for Location Change:</b>			

### Pit Inspection/Information Request:

<b>Field Inspection Date:</b>	<b>Document #:</b>
<b>Pit Still Present in Field:</b> No	
<b>Visible Surface Impacts:</b> <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
<b>Inspection Notes:</b>	
<b>Operator Required to Submit Form:</b> NA	<b>Due Date:</b>
<b>Form Request Sent To:</b>	<b>Sent Date:</b>

## Pit Status Evaluation:

### Pit Status Review Documents:

- |                                     |   |                  |
|-------------------------------------|---|------------------|
| <input type="checkbox"/>            | Form 15 Pit Permit – Doc #:                 | Date:            |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 656107         | Date: 12/3/1986  |
|                                     | Doc #: 563595                               | Date: 6/1/1998   |
|                                     | Doc #: 200118550                            | Date: 09/06/2007 |
| <input type="checkbox"/>            | Form 27 Remediation Workplan – Project #:   | Date:            |
| <input type="checkbox"/>            | Form 4 Sundry Notice – Doc #:               | Date:            |
| <input type="checkbox"/>            | COGIS Document – Doc #:                     | Date:            |
| <input type="checkbox"/>            | Pit Inventory – Doc #:                      | Date:            |
| <input type="checkbox"/>            | Duplicate Record – Duplicate Pit(s) #:      |                  |
| <input type="checkbox"/>            | Aerial Photo Verification (photos attached) |                  |
| <input type="checkbox"/>            | Other:                                      |                  |

### Pit Status Determination

**Updated Pit Status: Closed**


**Pit Status Date: 9/23/1999**

#### Timing of Pit Closure:

No evidence of a pit on location. Associated well PA 8/20/2010.

#### Pit Status Review Summary:

Based on records review there is no evidence that there was a pit on location; inspection reports document an open top fiberglass produced water tank on location. Associated well PA 8/20/2010. Pit status has been changed to closed.



2005

