

Pit Status Evaluation Form

Pit Overview:

Pit Name: JAMES 1	Facility ID: 115416
Current Status: Unknown	Status Date: 9/23/1999
Current Operator:	
Updated Operator:	
Form 15 Pit Permit Doc #:	Permit Date:
Related Facilities: JAMES #1 (API 05-063-06090 - Facility ID 213531 - Loc ID 385039)	

County: Kit Carson			
Township: 8s	Range: 43W	Section: 18	QQ: NENW
Original Latitude/ Longitude:		/	
Updated Latitude/ Longitude:		39.386729 / -102.158642	
Basis for Location Change:			
Created lat/long at well location			

Pit Inspection/Information Request:

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | | |
|-------------------------------------|---|-----------------|
| <input type="checkbox"/> | Form 15 Pit Permit – Doc #: | Date: |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 704674 | Date: 4/11/1985 |
| | Doc #: 450433 | Date: 7/13/1988 |
| | Doc #: 500145939 | Date: 3/17/1999 |
| <input type="checkbox"/> | Form 27 Remediation Workplan – Project #: | Date: |
| <input type="checkbox"/> | Form 4 Sundry Notice – Doc #: | Date: |
| <input checked="" type="checkbox"/> | COGIS Document – Doc #: 486206 | Date: 10/6/1997 |
| <input type="checkbox"/> | Pit Inventory – Doc #: | Date: |
| <input type="checkbox"/> | Duplicate Record – Duplicate Pit(s) #: | |
| <input checked="" type="checkbox"/> | Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> | Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date: 9/23/1999

Timing of Pit Closure:

Associated well was plugged and pit backfilled 2/7/1997

Pit Status Review Summary:

Inspection reports document a 20'x50' pit on location. Associated well was plugged and pit backfilled 2/7/1997 and passed final inspection 3/17/1999. Pit status has been changed to closed.

