

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402174218

Date Received:  
09/12/2019

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Beebe, Sabre SanJuanCOGCC@bp.com

Beebe, Sabre sabre.beebe@bpx.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 693900541

Inspection Date: 07/11/2019

FIR Submit Date: 07/22/2019

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

### LOCATION - Location ID: 325427

Location Name: NELEIGH-N34N7W Number: 7NESW County: LA PLATA

Qtrqr: NESW Sec: 7 Twp: 34N Range: 7W Meridian: N

Latitude: 37.227574 Longitude: -107.680321

### FACILITY - API Number: 05-067- -00 Facility ID: 214753

Facility Name: NELEIGH Number: 01-07 1

Qtrqr: NESW Sec: 7 Twp: 34N Range: 7W Meridian: N

Latitude: 37.227574 Longitude: -107.680321

### CORRECTIVE ACTIONS:

1 ☒ CA# 128393

Corrective Action: Control weeds.

Date: 08/05/2019

Response: CA COMPLETED

Date of Completion: 08/12/2019

Operator Comment: Weeds chemically treated

COGCC Decision: Approved pending re-inspection



Date: 9/12/2019 10:36:56 AM

## Page 2 of 2