

**Inspection Photos**  
**Location Name: Pawnee 16-13H**  
**Location ID: 420186**



**Photo 1 – Tank Battery**



**Photo 2 – Wellhead**



Inspection Photos  
Location Name: Pawnee 16-13H  
Location ID: 420186



**Photo 3 – Only sign on Location at Entrance, COGCC records show Whiting Oil & Gas Corp. is current Operator; not Extraction. Sign missing 24 hour Emergency Contact Info and Legals.**



**Photo 4 – Unused down hole tools.**





**Inspection Photos**  
**Location Name: Pawnee 16-13H**  
**Location ID: 420186**



**Photo 5 – Unused Polish Rod and wellhead parts**



**Photo 6 – Unused Equipment in the SE corner of Tank Berm**

