

Inspection Photos
Location Name: Nelson Ranches A1
Location ID: 326962



Photo 1 – Wellhead Sign




Photo 2 – Wellhead, Trash



Inspection Photos
Location Name: Nelson Ranches A1
Location ID: 326962



Photo 3 – NE Deadman – Not Marked



Photo 4 – SE Deadman – Not Marked

Inspection Photos
Location Name: Nelson Ranches A1
Location ID: 326962



Photo 5 – NW Deadman – Not Marked



Photo 6 – SW Deadman – Not Marked

Inspection Photos
Location Name: Nelson Ranches A1
Location ID: 326962



Photo 7 – Trash East of Wellhead



Photo 8 – Unused Tubing West of Wellhead

Inspection Photos
Location Name: Nelson Ranches A1
Location ID: 326962



Photo 9 – Unused Poly Liner on Lease Road



Photo 10 – Weeds around Wellhead