

Love Ranch 1
API: 05-103-09915
Inspection: 700400329



39.89086, -108.29129, 6065.2ft, 305°
03/05/2020 10:44:37 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

Love Ranch 1
API: 05-103-09915
Inspection: 700400329



39.8926, -108.29183, 6060.5ft, 270°
03/05/2020 10:29:18 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Out of service tank battery.

Love Ranch 1
API: 05-103-09915
Inspection: 700400329



39.89173, -108.2916, 6073.5ft, 344°
03/05/2020 10:22:57 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Well head.

Love Ranch 1
API: 05-103-09915
Inspection: 700400329



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Separator & support buildings.

Love Ranch 1
API: 05-103-09915
Inspection: 700400329



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 5. Vessel.

Love Ranch 1
API: 05-103-09915
Inspection: 700400329



39 89171, -108 29129, 6071 9ft, 341°
03/05/2020 10:22:17 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 6. Pig station.

Love Ranch 1
API: 05-103-09915
Inspection: 700400329



39.89116, -108.29149, 6082.4ft, 269°
03/05/2020 10:40:00 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 7. Active tank battery.

Love Ranch 1
API: 05-103-09915
Inspection: 700400329



39.89125, -108.29147, 6081.8ft, 283°
03/05/2020 10:43:39 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 8. Container & panel in front of active tank battery.