

RGU 12-10-298D
API: 05-103-10760
Inspection: 700400333



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Well head.

RGU 12-10-298D
API: 05-103-10760
Inspection: 700400333



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Separator.

RGU 12-10-298D
API: 05-103-10760
Inspection: 700400333



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Tank battery.

RGU 12-10-298D
API: 05-103-10760
Inspection: 700400333



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Unmarked deadman.

RGU 12-10-298D
API: 05-103-10760
Inspection: 700400333



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 5. Separator bird cone.