

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/05/2020

Submitted Date:

03/05/2020

Document Number:

700400329**FIELD INSPECTION FORM**Loc ID 316151 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 100264Name of Operator: XTO ENERGY INCAddress: 110 W 7TH STREETCity: FORTH WORTH State: TX Zip: 76102**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Secrest, Ken	435-828-1450	ken_secrest@xtoenergy.com	
West, Jerry		jerry_west@xtoenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232244	WELL	PR	05/31/2012	GW	103-09915	LOVE RANCH FEE 1	PR
446952	TANK BATTERY	AC	07/25/2016		-	LOVE RANCH FEE-62S97W 9SEW	AC

**General Comment:**[COGCC Inspection Report Summary.](#)[On 3-5-2020 at approximately 10:40, inspector Rick Moran, conducted a routine inspection at XTO Energy well Love Ranch 1 in Rio Blanco county.](#)[No corrective actions were identified.](#)[This is a summary of inspection report 700400329.](#)

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	LOCATION		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Pig stations.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Horizontal Separator	# 1		

Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 3		
Comment:	Storage container, vessel, and trash container.		
Corrective Action:		Date:	
Type: Pig Station	# 2		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 4		
Comment:	Containers of SCI-8760, MC MX 6-2719, diesel, and NaturaLine SS-5075.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
OTHER	2	400 BBLS	STEEL AST		39.892570,-108.291950	
Comment:	Out of service.					
Corrective Action:					Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent		Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
OTHER	2	200 BBLS	STEEL AST		39.892570,-108.291950	
Comment:	Out of service					
Corrective Action:					Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Inspector Name: Moran, Rick

Metal	Adequate	Walls Sufficent		Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	OTHER	STEEL AST		39.890940,-108.291490
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	750 bbl	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent		Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**Facility ID: 232244 Type: WELL API Number: 103-09915 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Facility ID: 446952 Type: TANK API Number: - Status: AC Insp. Status: AC**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Four 750 bbl tank battery.

Corrective Action:

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass			Material Handling And Spill Prevention	Pass	
Ditches	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700400330	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5087298">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5087298</a>