

Final Reclamation Inspection

February 25, 2020

Operator: HIGHPOINT ENERGY LLC - 10544

Location ID: 424350

Inspection Document #: 697501190

Weld County, CO

SENW Section 22 T6N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: 392 VENTURES PAD /CN-22
Location ID: 424350



Photo 1. Photo taken from the well and tank battery location, facing East. Photo illustrates Operator has removed all the major equipment but has not conducted surface reclamation (i.e., remove gravel, contour, ect...).

Inspection Photos
Location Name: 392 VENTURES PAD /CN-22
Location ID: 424350



Photo 2. Photo taken from the well and tank battery location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: 392 VENTURES PAD /CN-22
Location ID: 424350



Photo 3. Photo taken from the well and tank battery location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: 392 VENTURES PAD /CN-22
Location ID: 424350



Photo 4. Photo taken from the northeastern location, facing East. Photo illustrates unused equipment left at location.

Inspection Photos
Location Name: 392 VENTURES PAD /CN-22
Location ID: 424350



Photo 5. Photo taken from the northeastern location, facing East. Photo illustrates unused equipment left at location.

Inspection Photos
Location Name: 392 VENTURES PAD /CN-22
Location ID: 424350



Photo 6. Photo taken from the northern location, facing West. Photo illustrates spills left behind that have not been cleaned up.