

Pit Status Evaluation Form

Pit Overview:

Pit Name: COSSLETT GU "E"	Facility ID: 118026
Current Status: Unknown	Status Date: 9/23/1999
Current Operator: AMOCO PRODUCTION COMPANY / 2500	
Updated Operator:	
Form 15 Pit Permit Doc #: 382997	Permit Date: 11/28/1979
Related Facilities: COSSLETT 'E' GAS UNIT #1 (API 05-123-09478 - Facility ID 241689 - Loc ID 318594)	

County: WELD			
Township: 1N	Range: 68W	Section: 1	QQ: CSW
Original Latitude/ Longitude: 40.076717 / -104.956535			
Updated Latitude/ Longitude: /			
Basis for Location Change:			

Pit Inspection/Information Request:

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | |
|---|------------------|
| <input checked="" type="checkbox"/> Form 15 Pit Permit – Doc #: 382997 | Date: 11/28/1979 |
| <input checked="" type="checkbox"/> Field Inspection(s) – Doc #: 36104 | Date: 1/30/1995 |
| Doc #: 36087 | Date: 3/21/1996 |
| Doc #: 200219707 | Date: 5/27/2009 |
| <input type="checkbox"/> Form 27 Remediation Workplan – Project #: | Date: |
| <input type="checkbox"/> Form 4 Sundry Notice – Doc #: | Date: |
| <input type="checkbox"/> COGIS Document – Doc #: | Date: |
| <input checked="" type="checkbox"/> Pit Inventory – Doc #: 2142986 | Date: 8/25/1997 |
| <input type="checkbox"/> Duplicate Record – Duplicate Pit(s) #: | |
| <input checked="" type="checkbox"/> Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date: 9/23/1999

Timing of Pit Closure:

Pit replaced prior to 1/30/1995 inspection

Pit Status Review Summary:

Based on records review, any pits on location were closed prior to the 1/30/1995 field inspection; pit inventory and inspections document a fiberglass produced water tank on location. Pit status has been changed to closed.

