

**Inspection Photos**  
**Location Name: McCallum Unit 123**  
**Location ID: 324698**



**Photo 1. Access roads not maintained for winter.**

