

**Inspection Photos**  
**Location Name: Brown 11-8**  
**Location ID: 427862**



**Photo #1 pump jack**



**Photo #2 ECD and separator**



**Inspection Photos**  
**Location Name: Brown 11-8**  
**Location ID: 427862**



**Photo #3 stained soil under fire tube on separator**



**Photo #4 used plastic buckets in separator house**



# Inspection Photos Location Name: Brown 11-8 Location ID: 427862




Photo #5 meter card out of calibration date



Photo #6 tanks

Inspection Photos  
Location Name: Brown 11-8  
Location ID: 427862



Photo #7 north tank load out line missing bullplug



Photo #8 south tank load out line missing bullplug





**Inspection Photos**  
**Location Name: Brown 11-8**  
**Location ID: 427862**



**Photo #9 pulley guard missing on pump jack motor**