

Inspection Photos
Location Name: Brown 13-8
Location ID: 427862



Photo #1 pump jack



Photo #2 pulley guard missing from pump motor

