

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/06/2020

Submitted Date:

03/06/2020

Document Number:

701000156

FIELD INSPECTION FORM

Loc ID 310972 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10274
Name of Operator: PLATINUM GAS PROPERTIES LLC
Address: 6946 COUNTY RD T
City: KIRK State: CO Zip: 80824

Findings:

- 9 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Brenner, Roger	970-362-4204	argwmd@yahoo.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
297308	WELL	PR	12/18/2008	GW	125-11365	SIMMONS 34-11	PR

General Comment:

[Routine Inspection](#)

Location

Lease Road:			
Type	Access		
comment:	Gravel road through pasture		
Corrective Action		Date:	

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by wellhead		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Metal sign by water tank. Needs new labeling		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Metal panels around wellhead and metal shed		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Vertical Separator	# 1		
Comment:	Vertical gas separator in metal shed		
Corrective Action:		Date:	

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		39.891230,-102.160520
Comment:	Fiberglass water tank 50% buried 650' SW of wellhead next to CR 22				
Corrective Action:				Date:	

Paint

Condition:

Other (Content):

Other (Capacity): 120bbbls

Other (Type) _____	
--------------------	--

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date: <input style="width: 100px;" type="text"/>

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date: <input style="width: 100px;" type="text"/>

Flaring:

Type			
Comment:			
Corrective Action:			Date: <input style="width: 100px;" type="text"/>

Inspected Facilities

Facility ID: 297308 Type: WELL API Number: 125-11365 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Casing production. Central meter run for \(Simmons 34-11, 43-11, 44-11, Peters 44-10\) 2500' W @ Peters 44-10 \(39.89297/-102.16793\)](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Gravel	Pass			

Comment: [Location is grassed over](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT