

Inspection Photos

Location Name: WELLS RANCH USX AA-66N63W /23SWSW

Location #: 302200



Photo #1

Wells Ranch USX AA 23-25 (05-123-27347) Wellsite

Plugged & Abandoned | PA

~ 15 yds.

Reclamation progressing



Photo #2

Wells Ranch USX AA 23-25, 23-11, 23-12, 23-13, 23-14

Battery site

Abandoned: All Equipment Removed

Reclamation progressing