

Inspection Photos

Location Name: WELLS RANCH USX AA-66N63W /23NESW

Location #: 310824



Colorado Oil & Gas Conservation Commission
40.47021, -104.40671, 1455.0m, 35°
03/06/2020 05:23:59 PM

Photo #1

Wells Ranch USX AA 23-11 (05-123-27048) Wellsite

Plugged & Abandoned | PA

~ 25 yds.

Reclamation progressing



Colorado Oil & Gas Conservation Commission
40.46755, -104.40895, 1448.0m, 334°
03/06/2020 05:35:52 PM

Photo #2

Wells Ranch USX AA 23-25, 23-11, 23-12, 23-13, 23-14

Battery site

Abandoned: All Equipment Removed

Reclamation progressing