

## Inspection Photos

**Location Name:** WELLS RANCH USX AA-66N63W /23SWSW

**Location #:** 302621



Colorado Oil & Gas Conservation Commission  
40.46684, -104.41129, 1443.0m, 224°  
03/06/2020 05:30:46 PM

**Photo #1**

**Wells Ranch USX AA 23-13 (05-123-29490) Wellsite**

**Plugged & Abandoned | PA**

**~ 20 yds.**

*Reclamation progressing*



Colorado Oil & Gas Conservation Commission  
40.46755, -104.40895, 1448.0m, 334°  
03/06/2020 05:35:52 PM

**Photo #2**

**Wells Ranch USX AA 23-25, 23-11, 23-12, 23-13, 23-14**

**Battery site**

**Abandoned: All Equipment Removed**

*Reclamation progressing*