

Inspection Photos

Location Name: WELLS RANCH USX AA-66N63W /23SESW

Location #: 309998



Photo #1

Wells Ranch USX AA 23-14 (05-123-25725) Wellsite

Plugged & Abandoned | PA

~ 30 yds.

Reclamation progressing



Photo #2

Wells Ranch USX AA 23-25, 23-11, 23-12, 23-13, 23-14

Battery site

Abandoned: All Equipment Removed

Reclamation progressing