

Inspection Photos
Location Name: Unocal-Encana-66S96W 4NESW
Location ID: #335618
Inspection Date: February 28, 2020



Photo #1 – Facility sign.

Photo #2 – View of tank battery, looking east.



Inspection Photos
Location Name: Unocal-Encana-66S96W 4NESW
Location ID: #335618
Inspection Date: February 28, 2020



Photo #3 – Tank battery labels and placards.



Photo #4 – Snow and ice inside of secondary containment (southeast corner).



Inspection Photos

Location Name: Unocal-Encana-66S96W 4NESW

Location ID: #335618

Inspection Date: February 28, 2020



Photo #5 – SVE system remains west of tank battery. See Remediation Project #9489 for documentation.



Photo #6 – Fenced separator area.



Inspection Photos
Location Name: Unocal-Encana-66S96W 4NESW
Location ID: #335618
Inspection Date: February 28, 2020




Photo #7 – View of wellheads, looking west.

Photo #8 – Cones and excavations were present in former tank battery area west of wellheads on inspection date.

Note trash and debris (former tank battery liner fragments, circled) remaining in former tank battery area.



Inspection Photos

Location Name: Unocal-Encana-66S96W 4NESW

Location ID: #335618

Inspection Date: February 28, 2020



Photo #9 – Excavation in former tank battery area.



Photo #10 – Debris and ice in former tank battery area.



Inspection Photos

Location Name: Unocal-Encana-66S96W 4NESW

Location ID: #335618

Inspection Date: February 28, 2020



Photo #11 – Excavation and mesh debris in former tank battery area.



Photo #12 – Debris in former tank battery area.



Inspection Photos

Location Name: Unocal-Encana-66S96W 4NESW

Location ID: #335618

Inspection Date: February 28, 2020



Photo #13 – Debris in former tank battery area.



Photo #14 – Excavations in former tank battery area.



Inspection Photos

Location Name: Unocal-Encana-66S96W 4NESW

Location ID: #335618

Inspection Date: February 28, 2020



Photo #15 – Excavation and debris in former tank battery area.



Photo #16 – Excavation and debris in former tank battery area.

