

Inspection Photos
Location Name: Spill/Release Point ID #443921
REM # 9405



Conoco Phillips REM #9405 location photo.



Hilcorp valve maintenance sticker on gathering line.

Inspection Photos
Location Name: Spill/Release Point ID #443921
REM # 9405



Conoco Phillips valve can.



Valve can where Spill/Release Point ID #443921 occurred.