

Inspection Photos

API: 061-06296

Operator: STRACHAN EXPLORATION

Inspection Date: 3/6/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 061-06296 | Date: 3/6/2020

Inspection Photos



Photo 1. Facing southeast along the road. The road has been built up and graveled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06296 | Date: 3/6/2020

Inspection Photos



Photo 2. Facing toward the tank battery. The fence around the battery is maintained and secondary containment has been installed at pipe outlet.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06296 | Date: 3/6/2020

Inspection Photos



Photo 3. Facing south along toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06296 | Date: 3/6/2020

Inspection Photos



Photo 4. Well sign is posted at pumpjack.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06296 | Date: 3/6/2020