

Inspection Photos

3/6/2020

Operator: CHEVRON USA INC - 16700

Location ID: 414661

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 414661



Photo 1: Photo of well



Photo 2: Photo taken from anchor on the northeast corner of the Location. Rule 1003.a requires anchors to be identified by a marker of bright color not less than 4 feet in height. Markers in disrepair.



Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 414661



Photo 3: Photo taken from the east end of the Location. Photo shows trash debris within drainage.



Photo 4: Photo taken from the south end of the Location, facing east. Photo shows soil stockpile is not protected in accordance with 1002.c; erosion degradation evident.

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 414661



Photo 5: Photo taken from the north end of the Location. Photo shows what appears to be an electrical box; cables have been disconnected (see photo 6); Equipment is unused and needs to be removed in accordance with 603.f.



Photo 6: Continued from photo 5. Photo shows cables have been cut/disconnected.