


Inspection Photos  
Location Name: Matsushima 3-14  
Location ID: 322557



Tank battery



Wellhead



**Inspection Photos**  
**Location Name: Matsushima 3-14**  
**Location ID: 322557**



**Crude oil tank berm on 1/9/2020**



**Crude oil tank berm on 3/9/2020**