

Inspection Photos

API: 061-06806

Operator: NEWELL ENERGY LTD

Inspection Date: 3/6/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06806 | Date: 3/6/2020

Inspection Photos



Photo 1. Facing east toward the location. There are areas that are bare of vegetation and undesirable weeds.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06806 | Date: 3/6/2020

Inspection Photos



Photo 2. There is several red plastic couplers that remain at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06806 | Date: 3/6/2020

Inspection Photos



Photo 3. Facing north at the location. There is predominately undesirable weeds throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06806 | Date: 3/6/2020

Inspection Photos



Photo 4. Facing east at the location. There is predominately undesirable weeds throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06806 | Date: 3/6/2020

Inspection Photos



Photo 5. East side of the location facing north. This area is bare of vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06806 | Date: 3/6/2020

Inspection Photos



Photo 6. View of undesirable weeds (Kochia sp.) observed throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06806 | Date: 3/6/2020

Inspection Photos



Photo 7. Facing southwest toward the surrounding reference area which consists of desirable vegetation such as Blue grama, Sand dropseed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06806 | Date: 3/6/2020