

Inspection Photos

API: 061-06155

Operator: GRYNBERG PETROLEUM CO

Inspection Date: 3/5/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 061-06155 | Date: 3/5/2020

Inspection Photos




Photo 1. Facing south at the location. Vegetation has not adequately established at the location. There are areas bare of vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06155 | Date: 3/5/2020

Inspection Photos



Photo 2. There are areas of the location which are bare of vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06155 | Date: 3/5/2020

Inspection Photos



Photo 3. There are degraded wattles that remain at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06155 | Date: 3/5/2020

Inspection Photos



Photo 4. This area further south at the location is bare of vegetation approximately 60'x60'.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06155 | Date: 3/5/2020