

Inspection Photos  
Location Name: Rubyanna 13 Pad  
Location ID: 436071



Photo 1: Pumpjack Sign



Photo 2: Pumpjack

Inspection Photos  
Location Name: Rubyanna 13 Pad  
Location ID: 436071



Photo 3: Unused equipment/trash



Photo 4: Pumpjack Sign

Inspection Photos  
Location Name: Rubyanna 13 Pad  
Location ID: 436071



**Photo 5: Pumpjack**



**Photo 6: Unused equipment**

Inspection Photos  
Location Name: Rubyanna 13 Pad  
Location ID: 436071



Photo 7: Pumpjack Sign



Photo 8: Pumpjack

Inspection Photos  
Location Name: Rubyanna 13 Pad  
Location ID: 436071



Photo 9: Unused equipment



Photo 10: Pumpjack Sign

Inspection Photos  
Location Name: Rubyanna 13 Pad  
Location ID: 436071



Photo 11: Pumpjack



Photo 12: Unused equipment

Inspection Photos  
Location Name: Rubyanna 13 Pad  
Location ID: 436071



Photo 13: Pumpjack Sign



Photo 14: Pumpjack

Inspection Photos  
Location Name: Rubyanna 13 Pad  
Location ID: 436071



Colorado Oil and Gas Conservation Commission  
40.48198, -104.83322, 1451.5m, 279°  
Mar 9, 2020 11:47:03

Photo 15: Unused equipment



Colorado Oil and Gas Conservation Commission  
40.48209, -104.83322, 1450.1m, 305°  
Mar 9, 2020 11:47:31

Photo 16: Pumpjack Sign

**Inspection Photos**  
**Location Name: Rubyanna 13 Pad**  
**Location ID: 436071**



**Photo 19: Pumpjack**



**Photo 20: Unused equipment**

**Inspection Photos**  
**Location Name: Rubyanna 13 Pad**  
**Location ID: 436071**



**Photo 21: Unused equipment**



**Photo 22: Pumpjack Sign**

Inspection Photos  
Location Name: Rubyanna 13 Pad  
Location ID: 436071



Photo 23: Pumpjack



Photo 24: Stained soil

Inspection Photos  
Location Name: Rubyanna 13 Pad  
Location ID: 436071




Photo 25: Pumpjack Sign



Photo 26: Pumpjack

Inspection Photos  
Location Name: Rubyanna 13 Pad  
Location ID: 436071



Colorado Oil and Gas Conservation Commission  
40.48223, -104.83323, 1453.9m, 321°  
Mar 9, 2020 11:49:26

Photo 27: Stained soil



Colorado Oil and Gas Conservation Commission  
40.48286, -104.83285, 1459.5m, 92°  
Mar 9, 2020 12:21:33

Photo 28: Tank Battery Sign

Inspection Photos  
Location Name: Rubyanna 13 Pad  
Location ID: 436071



**Photo 29: Tank Battery**



**Photo 30: Unused equipment**

Inspection Photos  
Location Name: Rubyanna 13 Pad  
Location ID: 436071



**Photo 31: Disconnected gas meter house/unused riser**



**Photo 32: Unused risers**