

Inspection Photos
Location Name: Burr FD Pad 23-219HN
Location ID: 440510



Photo 1: Wellhead Sign



Photo 2: Wellhead

Inspection Photos
Location Name: Burr FD Pad 23-219HN
Location ID: 440510




Photo 3: Wellhead Sign



Photo 4: Wellhead



Inspection Photos
Location Name: Burr FD Pad 23-219HN
Location ID: 440510



Photo 5: Wellhead Sign




Photo 6: Wellhead



Inspection Photos
Location Name: Burr FD Pad 23-219HN
Location ID: 440510




Photo 7: Wellhead Sign



Photo 8: Wellhead



Inspection Photos
Location Name: Burr FD Pad 23-219HN
Location ID: 440510



Photo 9: Unused equipment



Photo 10: Wellhead Sign



Inspection Photos
Location Name: Burr FD Pad 23-219HN
Location ID: 440510




Photo 11: Wellhead



Photo 12: Unused equipment



Inspection Photos
Location Name: Burr FD Pad 23-219HN
Location ID: 440510



Photo 13: Trash



Photo 14: Wellhead Sign



Inspection Photos
Location Name: Burr FD Pad 23-219HN
Location ID: 440510



Photo 15: Wellhead



Photo 16: Wellhead Sign



Inspection Photos
Location Name: Burr FD Pad 23-219HN
Location ID: 440510



Photo 17: Wellhead




Photo 18: Wellhead Sign

Inspection Photos
Location Name: Burr FD Pad 23-219HN
Location ID: 440510



Photo 19: Wellhead



Photo 20: Tanks appear to be grounded



Inspection Photos
Location Name: Burr FD Pad 23-219HN
Location ID: 440510



Photo 21: Tank Battery Sign



Photo 22: Tank Battery



Inspection Photos
Location Name: Burr FD Pad 23-219HN
Location ID: 440510



Photo 23: Unused equipment



Photo 24: Unused equipment/trash



Inspection Photos
Location Name: Burr FD Pad 23-219HN
Location ID: 440510



Photo 25: (4)Crude oil tanks DO NOT contain NFPA placard



Photo 26: No NFPA placard on H2O tank



Inspection Photos
Location Name: Burr FD Pad 23-219HN
Location ID: 440510



Photo 27: No NFPA placard/labeling on wrong side of tank.



Photo 28: No NFPA placard/labeling on wrong side of tank.



Inspection Photos
Location Name: Burr FD Pad 23-219HN
Location ID: 440510



Photo 29: Unused riser



Photo 30: Unsused risers



Inspection Photos
Location Name: Burr FD Pad 23-219HN
Location ID: 440510



Photo 31: Unused risers




Photo 32: Unused riser



Inspection Photos
Location Name: Burr FD Pad 23-219HN
Location ID: 440510



Photo 33: Unused equipment




Photo 34: Unused equipment