

Inspection Photos

Loc#335044

Operator: Terra

Inspection Number: 692401964

Inspection Date: 2/28/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Views of Location.

February 28, 2020




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Fed RU Loc#335044



Photo#2:
Unmarked Anchor.



Photo#3:
Unmarked Anchor.

February 28, 2020