

Inspection Photos

API: 061-06742

Operator: NEWELL ENERGY LTD

Inspection Date: 3/5/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 061-06742 | Date: 3/5/2020

Inspection Photos



Photo 1. The well sign is posted at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06742 | Date: 3/5/2020

Inspection Photos



Photo 2. Facing northeast toward the tank battery at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06742 | Date: 3/5/2020

Inspection Photos



Photo 3. The berms at the tank battery has holes and is degraded. The fence around the tank battery is not maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06742 | Date: 3/5/2020

Inspection Photos



Photo 4. North side of the location facing southeast. The soils are bare of vegetation which extends out east from the tank battery.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06742 | Date: 3/5/2020

Inspection Photos



Photo 5. Facing west at the area which is bare of vegetation. It appears this area may have been impacted from a potential spill. This bare area extends 300 ft. downhill from the tank battery.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06742 | Date: 3/5/2020

Inspection Photos



Photo 6. This is a 2015 aerial image of the location which shows impacted area east of the well site and tank battery.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06742 | Date: 3/5/2020