

Inspection Photos

API: 061-06018

Operator: RENEGADE OIL & GAS COMPANY

Inspection Date: 3/5/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 061-06018 | Date: 3/5/2020

Inspection Photos



Photo 1. Facing west toward the location. The location is bare of vegetation and needs to be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06018 | Date: 3/5/2020

Inspection Photos



Photo 2. West side of the location facing east toward the location. The location is bare of vegetation and needs to be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06018 | Date: 3/5/2020

Inspection Photos



Photo 3. View of bare soil with no vegetation growth at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06018 | Date: 3/5/2020

Inspection Photos



Photo 4. Facing south toward the surrounding reference area which consists of Blue grama, Sand dropseed, Prairie threeawn among other native species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06018 | Date: 3/5/2020