

**Inspection Photos**  
**Location Name: Chalk Bluff 36-13H**  
**Location ID: 420168**



**Photo 1 – Tank Battery**



**Photo 2 – Oil sprayed over Pumping Unit**

**Inspection Photos**  
**Location Name: Chalk Bluff 36-13H**  
**Location ID: 420168**



**Photo 3 – Stained Soil on the Southside of Pumping Unit**



**Photo 2 – Stained Soil West of Wellhead**



**Inspection Photos**  
**Location Name: Chalk Bluff 36-13H**  
**Location ID: 420168**



**Photo 5 – Unused Workover Rig Equipment**



**Photo 2 – Stained Soil Pump**