

Inspection Photos
Location Name: Dietzler 10-14-9-60
Location ID: 423696



Photo 1 – Tank Battery



Photo 2 – Well

Inspection Photos
Location Name: Dietzler 10-14-9-60
Location ID: 423696



Photo 3 – Produced Water Tank – Missing Content and Capacity and NFPA Label has faded.

Photo 4 – 2 Middle Tanks – Missing Content and Capacity

Inspection Photos
Location Name: Dietzler 10-14-9-60
Location ID: 423696



Photo 5 – Stained Soil at SE corner of Pumping Unit