

Inspection Photos
Location Name: PA 44-13
Location ID: 457469
Inspection Date: March 6, 2020



PA 32-13 Operations Support Pad.



PA 32-13 Operations Support Pad.



Inspection Photos
Location Name: PA 44-13
Location ID: 457469
Inspection Date: March 6, 2020



PA 44-13 Pad



PA 44-13 Pad



Inspection Photos
Location Name: PA 44-13
Location ID: 457469
Inspection Date: March 6, 2020



Unlabeled steel AST.



Unlabeled steel AST, secondary containment in disrepair.

