

Inspection Photos
Location Name: Randall Creek 29 SESE
Location ID: 415877



Photo 1 – Tank Battery



Photo 2 – Separators

Inspection Photos
Location Name: Randall Creek 29 SESE
Location ID: 415877



Photo 3 – Signage



Photo 4 – 02-29H Wellhead

Inspection Photos
Location Name: Randall Creek 29 SESE
Location ID: 415877



Photo 5 – 503-2920H, 216-2920H, & 215-2920H Wellheads




Photo 6 – Tanks Missing Capacity

