

Location Name: – Wesco Operating Inc. – Rudnik Battery – Location ID 317096 - Rem #7897
Inspection Date: 03/02/2020



Photo # 1 –

Location Name: – Wesco Operating Inc. – Rudnik Battery – Location ID 317096 - Rem #7897
Inspection Date: 03/02/2020



Photo # 2 – Shallow trench leading out from under injection shed eastern wall

Location Name: – Wesco Operating Inc. – Rudnik Battery – Location ID 317096 - Rem #7897
Inspection Date: 03/02/2020



Photo # 3 – Head of shallow trench leading out from under injection house eastern wall at wet-dry line in soil

Location Name: – Wesco Operating Inc. – Rudnik Battery – Location ID 317096 - Rem #7897
Inspection Date: 03/02/2020



Photo # 4 – Seeding of surface as per Rem #11420 final reclamation

Location Name: – Wesco Operating Inc. – Rudnik Battery – Location ID 317096 - Rem #7897
Inspection Date: 03/02/2020



Photo # 5 –

Location Name: – Wesco Operating Inc. – Rudnik Battery – Location ID 317096 - Rem #7897
Inspection Date: 03/02/2020



Photo # 6 – Wet area around base of produced water tank extending from injection shed to containment berm

Location Name: – Wesco Operating Inc. – Rudnik Battery – Location ID 317096 - Rem #7897
Inspection Date: 03/02/2020



Photo # 7 – Wet area around base of concrete oil vault, staining on side of vault, appears to have overflowed

Location Name: – Wesco Operating Inc. – Rudnik Battery – Location ID 317096 - Rem #7897
Inspection Date: 03/02/2020



Photo # 8 – Wet area along west side of injection shed



Location Name: – Wesco Operating Inc. – Rudnik Battery – Location ID 317096 - Rem #7897
Inspection Date: 03/02/2020



Photo # 9 – Inner wall of containment berm, west side of injection shed, scraped significantly

Location Name: – Wesco Operating Inc. – Rudnik Battery – Location ID 317096 - Rem #7897
Inspection Date: 03/02/2020



Photo # 10 – Inner wall of containment berm, west side of injection shed, scraped significantly

Location Name: – Wesco Operating Inc. – Rudnik Battery – Location ID 317096 - Rem #7897
Inspection Date: 03/02/2020



Photo # 11 – Inner wall of containment berm, west side of injection shed, scraped significantly

Location Name: – Wesco Operating Inc. – Rudnik Battery – Location ID 317096 - Rem #7897
Inspection Date: 03/02/2020



Photo # 12 – Pipe on ground north side of separator and injection shed battery

Location Name: – Wesco Operating Inc. – Rudnik Battery – Location ID 317096 - Rem #7897
Inspection Date: 03/02/2020



Photo # 13 – Crude tank battery, backhoe on trailer

