

## Inspection Photos

Location Name: LARAMIE ENERGY LLC Griffith /14-2 Pad

Location ID: 312587



Photo #0748 from entrance to location



Photo #0750 Unused valve handle next to meter run.

## Inspection Photos

Location Name: LARAMIE ENERGY LLC Griffith /14-2 Pad

Location ID: 312587



**Photo #0751 Unused poly pipe next to tank battery**