

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/10/2020

Submitted Date:

03/10/2020

Document Number:

699800718**FIELD INSPECTION FORM**Loc ID 334551 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1401City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name    | Phone | Email                                 | Comment |
|-----------------|-------|---------------------------------------|---------|
| Murray, Richard |       | g.richard.murray@state.co.us          |         |
| Kellerby, Shaun |       | shaun.kellerby@state.co.us            |         |
| , Laramie       |       | cogccnotifications@laramie-energy.com |         |

**General Comment:**COGCC Inspection Report Summary

On Tuesday 3/10/20 at approximately 12:30 hours, I, Inspector Corey De Paolo, Conducted a domestic tap inspection at LARAMIE ENERGY LLC Domestic Tap /32-6 Pad, Location #455947 in Mesa County Colorado.

Refer to location #334551 for inventory, inspections and all other documents.

The domestic tap is derived from the sales line of the LARAMIE ENERGY LLC Mitchell /32-6 Pad. Location #334551. See photo #0738. The pressure is regulated with three in line regulators. See photo #0739. The first regulator is a 1" Kimray motor valve with a maximum working pressure of 300 psi. See photo #0740. The second regulator is a Fisher Big Joe with a pressure range of 90 to 150 psi. See photo #0742. The third regulator is a Fisher Little Joe with a pressure range of 15-40 psi. See photo #0744. The fittings appear to be 1000 and 2000 psi rated fittings. See photo #0741. The domestic tap supply services to the house to the South West of location with an address of 61687 60 1/2 Road Collbran CO 81624. Refer to document #401672926 for point of origin and point of delivery. This is a summary of inspection report.

**Location****Lease Road:**

|                    |        |       |  |
|--------------------|--------|-------|--|
| Type               | Access |       |  |
| comment:           |        |       |  |
| Corrective ActionL |        | Date: |  |

Overall Good: ☒**Emergency Contact Number:**

|                    |                            |       |  |
|--------------------|----------------------------|-------|--|
| Comment:           | Operators battery sign 911 | Date: |  |
| Corrective Action: |                            |       |  |

Overall Good: ☐**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                    | URL   |
|--------------|--------------------------------|---|
| 699800719    | Photos for Insp.<br>#699800718 | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5092102">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5092102</a> |