

Inspection Photos
Location Name: Windsor LV2 14-M Pad
Location ID: 449441



Photo 1: Wellhead Sign



Photo 2: Wellhead



Inspection Photos
Location Name: Windsor LV2 14-M Pad
Location ID: 449441



Photo 3: Wellhead Sign



Photo 4: Wellhead



Inspection Photos
Location Name: Windsor LV2 14-M Pad
Location ID: 449441



Photo 5: Wellhead Sign



Photo 6: Wellhead



Inspection Photos
Location Name: Windsor LV2 14-M Pad
Location ID: 449441



Photo 7: Stained soil



Photo 8: Wellhead Sign



Inspection Photos
Location Name: Windsor LV2 14-M Pad
Location ID: 449441



Photo 9: Wellhead



Photo 10: Wellhead Sign



Inspection Photos
Location Name: Windsor LV2 14-M Pad
Location ID: 449441



Photo 11: Wellhead



Photo 12: Wellhead Sign



Inspection Photos
Location Name: Windsor LV2 14-M Pad
Location ID: 449441



Photo 13: Wellhead




Photo 14: Stained soil



Inspection Photos
Location Name: Windsor LV2 14-M Pad
Location ID: 449441



Photo 15: Wellhead Sign



Photo 16: Wellhead



Inspection Photos
Location Name: Windsor LV2 14-M Pad
Location ID: 449441



Photo 17: Wellhead Sign



Photo 18: Wellhead



Inspection Photos
Location Name: Windsor LV2 14-M Pad
Location ID: 449441



Photo 19: Unused equipment at wellheads



Photo 20: Tank Battery Sign



Inspection Photos
Location Name: Windsor LV2 14-M Pad
Location ID: 449441



Photo 21: Tank Battery



Photo 22: Debris south of separators

Inspection Photos
Location Name: Windsor LV2 14-M Pad
Location ID: 449441



Photo 23: Debris in separator berm (north east corner)



Photo 24: Unused equipment



Inspection Photos
Location Name: Windsor LV2 14-M Pad
Location ID: 449441



Photo 25: Unused equipment



Photo 26: Unused riser



Inspection Photos
Location Name: Windsor LV2 14-M Pad
Location ID: 449441



Photo 27: Barrel not in containment

