

SEELEY OIL COMPANY LLC – 10506
API# 05-083-06539 ISLAND BUTTE II #6
Inspection Date : 3/10/2020



**Temporarily abandoned wellhead with sign.
MIT to maintain SI/TA status.**



Tubing gauge prior to test

SEELEY OIL COMPANY LLC – 10506
API# 05-083-06539 ISLAND BUTTE II #6
Inspection Date : 3/10/2020



Casing gauge at beginning of test



Casing gauge at end of test.