

Location Name: – Investment Equipment – WT Davis State Battery – Pit ID 107546 - Spill
Inspection Date: 03/02/2020



Photo # 1 –

Location Name: – Investment Equipment – WT Davis State Battery – Pit ID 107546 - Spill
Inspection Date: 03/02/2020



Photo # 2 – Crude oil tank battery south side view east

Location Name: – Investment Equipment – WT Davis State Battery – Pit ID 107546 - Spill
Inspection Date: 03/02/2020



Photo # 3 – Crude oil tank battery southeast corner view northwest. Animal burrows in the berm

Location Name: – Investment Equipment – WT Davis State Battery – Pit ID 107546 - Spill
Inspection Date: 03/02/2020



Photo # 4 –

Location Name: – Investment Equipment – WT Davis State Battery – Pit ID 107546 - Spill
Inspection Date: 03/02/2020



Photo # 5 – Produced water tank view southeast

Location Name: – Investment Equipment – WT Davis State Battery – Pit ID 107546 - Spill
Inspection Date: 03/02/2020



Photo # 6 – Produced water pit view south

Location Name: – Investment Equipment – WT Davis State Battery – Pit ID 107546 - Spill
Inspection Date: 03/02/2020



Photo # 7 – Produced water pit north berm repair/maintenance view east.

Location Name: – Investment Equipment – WT Davis State Battery – Pit ID 107546 - Spill
Inspection Date: 03/02/2020



Photo # 8 – Produced water pit view southeast.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: – Investment Equipment – WT Davis State Battery – Pit ID 107546 - Spill
Inspection Date: 03/02/2020



Photo # 9 – Produced water pit northeast corner view east.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: – Investment Equipment – WT Davis State Battery – Pit ID 107546 - Spill
Inspection Date: 03/02/2020



Photo # 10 – Produced water pit northeast corner view southeast.

Location Name: – Investment Equipment – WT Davis State Battery – Pit ID 107546 - Spill
Inspection Date: 03/02/2020



Photo # 11 – Produced water pit northeast corner view south.

Location Name: – Investment Equipment – WT Davis State Battery – Pit ID 107546 - Spill
Inspection Date: 03/02/2020



Photo # 12 – Produced water pit spill path view south-southeast.

Location Name: – Investment Equipment – WT Davis State Battery – Pit ID 107546 - Spill
Inspection Date: 03/02/2020



Photo # 13 – Produced water pit spill path view south-southeast.

Location Name: – Investment Equipment – WT Davis State Battery – Pit ID 107546 - Spill
Inspection Date: 03/02/2020



Photo # 14 – Produced water pit spill path view south

Location Name: – Investment Equipment – WT Davis State Battery – Pit ID 107546 - Spill
Inspection Date: 03/02/2020



Photo # 15 – Produced water pit spill path view east

Location Name: – Investment Equipment – WT Davis State Battery – Pit ID 107546 - Spill
Inspection Date: 03/02/2020



Photo # 16 – Produced water pit spill path view east

Location Name: – Investment Equipment – WT Davis State Battery – Pit ID 107546 - Spill
Inspection Date: 03/02/2020



Photo # 17 – Produced water pit spill path view southwest

Location Name: – Investment Equipment – WT Davis State Battery – Pit ID 107546 - Spill
Inspection Date: 03/02/2020



Photo # 17 – Produced water pit spill path view south



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: – Investment Equipment – WT Davis State Battery – Pit ID 107546 - Spill
Inspection Date: 03/02/2020



Photo # 19 – Produced water pit spill path view east-southeast

Location Name: – Investment Equipment – WT Davis State Battery – Pit ID 107546 - Spill
Inspection Date: 03/02/2020



Photo # 20 – Produced water pit spill path view south along CR HH

Location Name: – Investment Equipment – WT Davis State Battery – Pit ID 107546 - Spill
Inspection Date: 03/02/2020



Photo # 21 – Produced water pit spill path view south along CR HH

Location Name: – Investment Equipment – WT Davis State Battery – Pit ID 107546 - Spill
Inspection Date: 03/02/2020



Photo # 22 – Produced water pit spill path view south along CR HH

Location Name: – Investment Equipment – WT Davis State Battery – Pit ID 107546 - Spill
Inspection Date: 03/02/2020



Photo # 23 – Produced water pit spill path termination west of CR HH, view north



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: – Investment Equipment – WT Davis State Battery – Pit ID 107546 - Spill
Inspection Date: 03/02/2020



Photo # 24 – Produced water pit east berm animal burrows



Location Name: – Investment Equipment – WT Davis State Battery – Pit ID 107546 - Spill
Inspection Date: 03/02/2020



Photo # 25 – Produced water pit south berm animal burrow



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: – Investment Equipment – WT Davis State Battery – Pit ID 107546 - Spill
Inspection Date: 03/02/2020



Photo # 26 – Produced water pit south berm animal burrow

Location Name: – Investment Equipment – WT Davis State Battery – Pit ID 107546 - Spill
Inspection Date: 03/02/2020



Photo # 27 – Produced water pit south berm animal burrow



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources