

# Inspection Photos

3/11/2020

Operator: RIO MESA RESOURCES INC - 74740

Location ID: 398846

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

## Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 398846



**Photo 1:** Photo taken from the west end of the location, facing northeast. Photos 1-4 provide an overview of the Location from Northeast, east, southeast to south. Photo shows additional reclamation activities appear to have been conducted.



**Photo 2:** See comments under photo 1.



## Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 398846



**Photo 3:** See comments under photo 1.



**Photo 4:** See comments under photo 1.



**Inspection Photos**  
**Operator Name: RIO MESA RESOURCES INC - 74740**  
**Location ID: 398846**



**Photo 5:** Photo of trash debris observed on the western end of the Location.



**Photo 6:** Photo taken from the east end of the Location, facing west. Photo shows Operator installed tracking on the slopes of the reclamation areas; Tracking is a temporary control and will not be sufficient for long term stabilization until vegetation has established. Tracking should also be used in conjunction with other BMPs per good engineering practices.



## Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 398846



**Photo 7:** Photo taken from the north end of the Location, facing west. Photo shows areas at risk to erosion.



**Photo 8:** Photo shows Location appears to have been broadcast seeded.



## Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 398846



**Photo 9:** Photo taken from the north end of the Location, facing north. Photo shows access road has not been reclaimed per corrective actions.



**Photo 10:** Photo taken from the west end of the Location, facing west. Photo shows access road has not been reclaimed per corrective actions.

Inspection Photos  
Operator Name: RIO MESA RESOURCES INC - 74740  
Location ID: 398846



**Photo 11:** Google earth aerial image. Photo shows access road(s) leading to Location that has not been reclaimed.

