

Inspection Photos

Location Name: ANTOINETTE 42-30

API#: 05-071-07256

INSP. #: 695102291



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN

Inspection Photos
Location Name: ANTOINETTE 42-30
API#: 05-071-07256
INSP. #: 695102291

Calibration Report

Report Date: 4/22/19 11:17 AM Collection Time: 4/22/19 11:14 AM

Device ID: 101-101-000 Location: Antoinette 42-30

System: Contact # 715-548-7058 Field: Raton Basin State: Colorado Producer: Evergreen Natural Resources Purchaser: Colorado Interstate Gas

Calibration Data:

Date	Time	Calibration	Specific Gravity
4/22/19	11:14	5.56	5.56

Gas Sample Taken 11:14 AM 4/22/19

H2S analysis done 0 Yes 11 No

PPM or %

4/22/2019

Colorado Oil & Gas Conservation Commission
37.14447, -104.7058, 2025.0m, 207°
2020/03/11 13:00:57

PHOTO 3: GAS METER CAL. REPORT

