

Inspection Photos

Location Name: GM 34-33

Location ID: 334868 & Spill/Release ID: 447506

Inspection Date: March 11, 2020



Location sign.



Photo from 8/29/2016 of the landfarm looking southwest (Doc #674300758).



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: GM 34-33

Location ID: 334868 & Spill/Release ID: 447506

Inspection Date: March 11, 2020



Photo of where the landfarm was located looking southwest.



Photo from 8/29/2016 of the excavation on location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: GM 34-33

Location ID: 334868 & Spill/Release ID: 447506

Inspection Date: March 11, 2020



Photo of a Produced Water steel AST where the excavation was located on 8/29/2016.



Photo from 8/29/2016 of Biosorb that was staged on location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources