

Inspection Photos
Operator: BP America
API#: 067-06326
Date: 3/10/2020



Photo 1. View of plugged well marker facing southward. Tubing and electrical equipment remain in place.



Photo 2. View of the southern portion of the project area facing southwestward. Equipment remains in place, well pad needs reclamation.



Photo 3. View of the northern project area facing northwestward. Well pad needs reclamation.



Photo 4. View of reference area vegetation comprised of sagebrush shrubland with grassy understory, dominated by thickspike wheatgrass, and James galleta.