

Inspection Photos
Operator: BP America
API#: 067-09699
Date: 3/10/2020



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward. Revegetation is progressing in portions of the outer reclamation areas with grasses such as intermediate wheatgrass.



Photo 3. View of area within the eastern reclamation area needing to stabilization with revegetation.




Photo 4. View of musk thistles within the northeastern project area. Approximately 100 individuals observed.



Photo 5. View of reference area vegetation (in background) comprised of open grass field with grasses such as western wheatgrass.