

Inspection Photos

ID: 262144

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 3/12/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

ID: 262144 | Date: 3/12/2020

Inspection Photos



Photo 1. There is an open excavation near the LORENCITO / 14-16-34-66 pit. This excavation needs to be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 262144 | Date: 3/12/2020

Inspection Photos



Photo 2. The open excavation area is about 4 ft. deep. Weeds have grown in this area during previous growing season.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 262144 | Date: 3/12/2020

Inspection Photos



Photo 3. The excavation area is at the south side of the LORENCITO / 14-16-34-66 pit.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 262144 | Date: 3/12/2020

Inspection Photos



Photo 4. Facing northeast toward the LORENCITO / 14-16-34-66 pit.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 262144 | Date: 3/12/2020